




ADRIAN STEEL CO.
906 JAMES STREET
ADRIAN, MI 49221
517/265-6194

TK 30
STOW-ALL TRACTION KIT
APPLICATION INSTRUCTION
"TRIPLE SA30/SAJ30"

DWG BY	ECN#	DATE	CHK BY	PACKAGE #	ISS.
KAS	6071	8/29/02	WV	S/L TK30	A
PACKAGE WEIGHT-		000.00 #	REF. 15769		
			HCG= 00 VCG= 00		
ITEM	PART NO.	DESCRIPTION			QTY.
1	27846	TRACTION STRIP-DIE CUT, 4 X 51			5



APPLICATION STEPS:

- 1) CLEAN TOP SURFACE OF STOW-ALL GETTING RID OF ANY DIRT, DEBRIS, OR FINGER PRINTS.
(SURFACE MUST BE CLEAN FOR PROPER ADHESION OF TRACTION STRIPS.)
- 2) PARTIALLY "PEEL OFF BACKING" OF TRACTION STRIP AND APPLY STICKY END TO FRONT OR BACK
EDGE OF STOW-ALL AT THE DIMENSIONS SHOWN ABOVE.
- 3) ONCE TRACTION STRIP IS SECURE AT THE FRONT OR BACK EDGE OF STOW-ALL, PEEL OFF BACKING WHILE
FIRMLY TACKING DOWN REMAINDER OF TRACTION STRIP KEEPING ALIGNED WITH SIDE EDGE OF STOW-ALL AND
ADJACENT TRACTION STRIP. BE SURE TO "ROLL" OR "PRESS" OUT ALL EDGE GAPS AND BUBBLES.

CAUTION:
DRILL THRU FLOOR WITH CARE
WATCH FOR GAS TANK, CONTROL
LINES, & ELECTRICAL WIRING.

(SCALE: 3/32)